



# Joint ANL/FNAL SCPF and BCP System Update

Allan Rowe Fermilab AD/MSD

August 4, 2006



## **UPW System**

- System is operating and recirculating on itself
- Anion/cation and divalent metal concentration + dissolved silica tests were performed by installer. Results are within UPW quality specs.
- A second, more thorough test through Balazs
   Analytical Lab, verified that system produces
   UPW within specification.
- Official 'turn-on' occurred week of July 10, 2006.






## **BCP System**







### Full water commissioning revealed the following:

- Acid cooling scheme required modification
- > Room egress was not within life-safety requirements
- > Too many overhead lines
- Extra features in system could be eliminated to improve simplicity
- ➤ Large cavity handling required architectural change
- Controls simplifications required for operator 'comfort'









## BCP System----Major Improvements

- Eliminated residual acid storage in system
- Pre-cool and pre-meter acid
- Direct acid feed from supply drum
- Reduced acid/water plumbing
- Follows life-safety rules
- Simplified process heat exchange\*
- Reduced overall system complexity
- Modified layout to accept 1.3 GHz cavities

## BCP System---Costs & Manpower

- Estimated M&S remaining in FY06 = \$50k\*
- Estimated SWF remaining in FY06 = 1.25
   FTE

\* At least 1 FTE and \$100k for cavity hardware and cleanroom gear will be required in FY'07